United States of America

Department of Transportation -- Federal Abiation Administration

Supplemental Type Certificate

Number SRO9555RC

This certificate issued to

Heritage Aviation, LTD 2626 Aviation Parkway Grand Prairie, TX 75052

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 21 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number:

MD Helicopters

Model.

MD 900

Description of Type Design Change:

Installation of an EMS Interior in accordance with Heritage Aviation, Ltd. Master Drawing List, EMS Interior, A00-13005, Revision F, dated July 13, 2009, or later FAA approved revision. Rotorcraft Flight Manual Supplement, Document No. A09-63003, Revision B, dated July 20, 2009, or later FAA approved revision is required. Instructions for Continued Airworthiness, Document No. A04-73006, Revision A, dated May 15, 2009 or later revision is required.

Limitations and Conditions:

This installation is compatible with MD900 S/N 900-00010 thru 900-99999 only. (See continuation sheet 3 of 3)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration

Date of application: April 16, 2008

Date of issuance: July 20, 2009

Date reissued:

Date amended:

By direction of the Administrator

Charles C. Harrison, Acting Manager Rotorcraft Certification Office

Southwest Region

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

INSTRUCTIONS: The transfer endorsement below may be used to notify the appropriate FAA Regional Office of the transfer of this Supplemental Type Certificate.

The FAA will reissue the certificate in the name of the transferee and forward it to him.

TRANSFER ENDORSEMENT

Transfer the ownership of Supplemental Type Certificate Number
to (Name of transferee)
(Address of transferee)(Number and street)
(City, State, and ZIP code)
from (Name of grantor) (Print or type)
(Address of grantor) (Number and street)
(City, State, and ZIP code)
Extent of Authority (if licensing agreement):
Extent of Additionty (if Inclising agreement).
<u> </u>
Date of Transfer:
Signature of grantor (In ink):

United States of America

Department of Transportation -- Federal Abiation Administration

Supplemental Type Certificate

(Continuation Sheet)

Number srogsssrc

Date of Issuance: July 20, 2009

Limitations and Conditions (Continued):

The Heritage Aviation, Ltd. Utility Floor Installation STC SR09554RC is a PREREQUISITE for this installation.

The Heritage Aviation, Ltd. Medical Oxygen System Installation STC SR09556RC IS REQUIRED to be installed in conjunction with the EMS Interior Installation.

The Air Methods Corporation (AMC) Articulating Patient Litter System STC SR00243DE-D with AMC Litter P/N 108-1080 is approved for installation in conjunction with this modification.

The following seating configurations are approved in accordance with the EMS Interior Installation: A57-13002-01, -05, -06, -09, -10, -11, and -12 seating configurations

The following seating configurations have not been evaluated and are $\underline{\text{NOT APPROVED}}$ for installation: A57-13002-03 and -07

Compatibility of this design change with previously approved modifications must be determined by the installer. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the person written evidence of that permission.